Product Release Notice
ErisTerminal™ 1.0.5A Firmware

Release Date: July 2015

This document contains the release notes for VTech ErisTerminal version 1.0.5A. This upgrade release includes significant enhancements; therefore, users of previous ErisTerminal releases are encouraged to upgrade. The following topics are detailed below.

What's new?
Recent changes
How to upgrade
Version Compatibility
Manuals
Product support

What's new?

With the release of 1.0.5A, the following features have been added. Numbers in parentheses indicate VTech's internal tracking ticket number.

Updates for Metaswitch and Simplitalk Interoperability
- Added interoperability with Freeswitch-based servers.

VTech redirection server now available (#1869)
- By default ErisTerminal devices are configured with a provisioning URL that directs a new phone to the VTech redirection server upon joining a network. For more information, contact the VTech sales or support team.

Recent Changes

All products:

Description	Reference Number
Corrected bug where long URLs of 256 characters in the provisioning server sometimes were not saved properly.	#1261, 1895
When configured for Metaswitch shared lines, corrected failed outgoing call occurring after the first outbound call.	#1693
Introduced Account Label for identifying line/account instead of using the User ID.	#2053

VSP725 and/or VSP735:

Description	Reference Number
BLF pickup method now uses the 'entity' attribute instead of the 'id' attribute.	#1805
New "freeswitch" BLF variant has been created.	#670
Local HOLD state now has higher priority than the REMOTE HOLD state (far-end). This allows the near-end user to resume the held call.	#1686
For Freeswitch variant, introduced the processing of sip.rendering in order to indicate monitored extension held state, allowing the held call to be remotely picked up by other extensions.	#1728, 1897
Sped up network throughput on the VSP725 PC port.	#1485, 1829

VSP600/VSP601:

Description	Reference Number
Fixed soft keys associated with incoming call from appearing when the user lifts the handsets from the charger after the far end callers have hung up the call.	#1378, 1868
Fixed issue with sampling ringtones in the Ringer menu when ring volume is off.	#1865
Fixed issue with persistent "System update in progress…" message after base station firmware update.	#1866
Fixed issue with handset displaying the setting when No Ans. Delay menu is highlighted.	1867

How to upgrade

Please refer to the Administrator and Provisioning Manual for your ErisTerminal product, available [here](#).

Version Compatibility

Version 1.0.5A is compatible with previous versions.

Manuals

For more information on the features described herein, please reference the Synapse manuals and technical documents located here: http://businessphones.vtech.com/support/manuals

Product support

For additional questions, please contact the VTech Business Phones team. Contact information is available here: http://businessphones.vtech.com/support/contact-us