vtech

Product Release Notice ErisTerminal[®] 1.1.2.0 Firmware

Release Date: April 2016

This document contains the release notes for VTech ErisTerminal version 1.1.2.0. This upgrade release, affecting the VSP715, VSP725 and VSP735 SIP Desksets, the VSP600 SIP DECT Base Station and Cordless Handset and the VCS754 Conference Phone, includes significant enhancements; therefore, users of previous ErisTerminal releases are encouraged to upgrade. The following topics are detailed below.

What's new? Recent changes Configuration file parameter changes How to upgrade Version compatibility Manuals Product support

What's new?

No new features have been added for the release of 1.1.2.0.

Recent changes

All products:

Description	Reference Number
Changed directory "Home" field to "Other" field.	#417
Fixed dial plan substitution behaviour.	#2032
Changed user_pref.call_terminated.busy_tone_enable to only apply to far-end call termination and network error condition.	#2048, #2651
Hotline feature now has a configurable account for dialing out (VSP600/600A not affected).	#2088
Fixed LDAP search failures and disconnection.	#2382
Increased URI string length for SIP contact ID.	#2468
New feature: "program dial" programmable soft key (VSP600/600A not affected).	#2424
Changed dial plan behaviour to separate "dial now" action and digit substitution.	#1230
When Missed Call LED is enabled, fixed LED from not being cleared properly.	#2327

Page | 1

businessphones.vtech.com/

© 2016 VTech Communications, Inc.

ErisTerminal®, ErisStation®, ErisBusinessSystem™ and Orbitlink Wireless Technology™ are trademarks of VTech Communications, Inc. All other marks are the property of their respective owners.

All rights reserved. $\mathsf{VTech}{}^{\texttt{R}}$ is a registered trademark of VTech Holdings Ltd.

vtech

Fixed SRTP handling.	#2439
Improved key-press tone response time.	#2516
Eliminated WebUI warning message (re: passwords in plain text) when exporting a configuration file when password exporting is disabled.	#2372
Fixed bug that caused long bootup time for cases when there are no provisioning files.	#2051
Modified "Expires" header handling to avoid deregistration issues.	#2309
Fixed issue with incoming call screen hanging when an incoming call is cancelled before the far end sends "Ringing".	#2544

VSP715, VSP725 and VSP735:

Description	Reference Number
Applied BLF blinking behaviour when BLF subscription fails.	#1820
Fixed 802.1x pass-through to the deskset PC port.	#2211
Corrected issue with decrypting SRTP with Early Media.	#2377
Added notification on deskset screen while updating DECT handset firmware.	#1012
Fixed issue with outgoing G.729 calls incorrectly activating Annex B.	#2379
VSP735 DND key now dials FAC to turn DND on/off on default account.	#2511
Fixed SELECT softkey availability when conferencing with or transferring to a held call.	#1714
Split WebUI programmable keys pages to improve WebUI performance.	#2422, #2459
Fixed issue with BLF key LEDs not indicating the correct subscription status.	#2477
Fixed problem with Asterisk server creating unintended unsubscribe interval for BLF keys when PFK key functions are modified.	#2563
Fixed issue with blind transfers using Call Log, Directory, BLF, or Quick Dial.	#1273
Added Prefix Dialing to PFK options.	#1970

VSP600/601:

Description	Reference Number
Added local Music on Hold (playback of tone when active call is remotely held).	#696
Fixed display of correct Caller ID information when calls are forwarded.	#2040

Page | 2

businessphones.vtech.com/

© 2016 VTech Communications, Inc.

All rights reserved. VTech® is a registered trademark of VTech Holdings Ltd. ErisTerminal®, ErisStation®, ErisBusinessSystem[™] and Orbitlink Wireless Technology[™] are trademarks of VTech Communications, Inc. All other marks are the property of their respective owners.

vtech

VCS754:

5754.		
Description	Reference Number	
Corrected issue with decrypting SRTP with Early Media.	#2377	
Fixed issue with outgoing G.729 calls incorrectly activating Annex B.	#2379	
Fixed SELECT softkey availability when conferencing with or transferring to a held call.	#1714	
Fixed multipurpose LED behaviour after listening or deleting new message.	#2212	
Hotline feature now has a configurable account for dialing out.	#2088	

Configuration file parameter changes

The following configuration file parameters have been introduced or modified in 1.1.2.0.

DIR_ENTRY_NUMBER_OTHER BLACKLIST_ENTRY_NUMBER_OTHER	Renamed parameters
Idap_other_number_attributes	Renamed parameter
sip_account.x.music_on_hold_enable	New parameter for VSP600
user_pref.call_terminated.busy_tone_enable	Modified: disabled by default
pfk.x.feature	Modified: busy lamp field allowed for pfk.4 to pfk.12 (VSP725) and pfk.6 to pfk.14 (VSP735) prefix dial added as a new pfk type.
pfk.x.prefix	New parameter
call_settings.hotline_account	New parameter
softkey.program_dial.x.label	New parameter
softkey.program_dial.x.number	New parameter
softkey.program_dial.x.account	New parameter

How to upgrade

Please refer to the Administrator and Provisioning Manual for your ErisTerminal product, available here.

Version compatibility

Version 1.1.2.0 is compatible with previous versions.

Manuals

For more information on the features described in this document, please reference the manuals and technical documents located here: <u>http://businessphones.vtech.com/support/manuals</u>

Product support

For additional questions, please contact the VTech Business Phones team. Contact information is available here: <u>http://businessphones.vtech.com/support/contact-us</u>

Page | 3

businessphones.vtech.com/

© 2016 VTech Communications, Inc.

All rights reserved. VTech $\ensuremath{\mathbb{B}}$ is a registered trademark of VTech Holdings Ltd.

ErisTerminal®, ErisStation®, ErisBusinessSystem™ and Orbitlink Wireless Technology™ are trademarks of VTech Communications, Inc. All other marks are the property of their respective owners.