



Product Release Notice

ErisTerminal® VDP650/651/658 v1.0.0.8 Firmware

Release Date: September 2018

This document contains the release notes for VTech VDP650, VDP651 and VDP658 version 1.0.0.8. This release contains feature enhancements and bug fixes. Users of previous releases are encouraged to upgrade.

Contents

Product Release Notice.....	1
ErisTerminal® VDP650/651/658 v1.0.0.8 Firmware.....	1
What’s new?.....	2
Recent Changes.....	2
Configuration file parameter changes	2
How to upgrade.....	3
Version Compatibility.....	3
Manuals.....	3
Product Support.....	3



What's new?

With the release of 1.0.0.8, the following features have been added. Numbers in parentheses indicate VTech's internal tracking ticket number.

Added capability for all accounts to share the same local sip port (#E5936)

- This feature is controlled by the following parameters:

Parameters	Possible values	Defaults	Exportable	WUI/PUI
sip_account.share_local_port_enable	0, 1	0	yes	not available
sip_account.shared_local_sip_port	any	5060	yes	not available

Added capability to set the programmable Lx keys on the cordless devices using the WebUI

- The admin can now use the WebUI to configure the programmable keys on the cordless devices. Prior to this addition the admin could only configure this via provisioning.

Recent Changes

All products:

Description	Reference Number
Corrected DHCP request delay when LLDP and 802.1x are enabled	#E6020
Corrected erroneous error message on the WebUI Trusted Certificate page	#E6016
Corrected phone incorrect behaviour when SRTP is enabled	#P5943
Corrected incoming caller info is now properly matched to the corresponding LDAP name Entry	#E6028
Removed race condition when line 1 is taken off hold at the same time line 2 far end hangs up causing line 1 call termination with the user interface showing line 1 active.	#E5998
Added capability for all accounts to share the same SIP local port	#E5936
Corrected random resumed held call from loss of audio to the far end	#E5782
Added capability to set the programmable Lx keys on the cordless devices using the WebUI	#P5782
Corrected the missing call waiting alert tone during and active call	#P6011

Configuration file parameter changes

The following configuration file parameters have been introduced or modified in 1.0.0.8:

sip_account.share_local_port_enable	New Parameter
sip_account.shared_local_sip_port	New Parameter



How to upgrade

Please refer to the Administrator and Provisioning Manual for your ErisTerminal product, available at <https://businessphones.vtech.com/support/downloads>

Version Compatibility

Partial compatibility may exist with the older versions between devices it is recommended that the VDP650, VDP651 and VDP658 are upgraded to the same Version 1.0.0.8. Backward compatibility with older versions is not tested and cannot be guaranteed.

Manuals

For more information on the features described in this document, please reference the manuals and technical documents located here:

<https://businessphones.vtech.com/support/downloads>

Product Support

For additional questions, please contact the VTech Business Phones team. Contact information is available here: <https://businessphones.vtech.com/support/contact-us>